




Spare part list

Weedbrush

WeeDo



Order number: E00064 From machine No.: 52824 Rev.: R01 Date: 18.06.2015




Manufactures by
Kersten Arealmaschinen GmbH
Empeler Straße 95
D - 46459 Rees
www.kersten-maschinen.de



Distributed in UK by
Kersten (UK) Ltd Tel. 0118 986 9253
Progrees House 39 Boulton Road
Reading, RG2 0NH
www.kerstenuk.com - info@kerstenuk.com

1	MODEL OVERVIEW	3
1.1	WEEDO - C04219 R00.....	3
2	ASSEMBLY OVERVIEW.....	4
2.1	ASSEMBLY FOR WEEDO - C04220 R00	4
2.2	BASIC CASE FOR WEEDO - C04228 R00	6
2.3	ATTACHMENT TO WEEDO- C04221 R01	7
2.4	HONDA MOTOR GVC 160 WEEDOH - C04227 R00	8
2.5	CONTROL CONSOLE FOR WEEDO - C04229 R00	9
2.6	SPRING PROTECTION WEEDO - C04222 R00	10
3	BESATZARTEN TYPES AND ATTACHMENTS.....	13
4	ACCESSORIES	14
4.1	SHIPPER FRAMEWORK – C05458 R00	14

1 Model Overview




1.1 WeeDo - C04219 R00

No.	Art.-No.	Num.	Designation
1	C04220 R01	1	Assembly
2	C04221 R01	1	Basic unit
3	C04228 R00	1	Headers
4	C04223 R01	1	Brush plate with trimming
5	C04227 R00	1	Honda engine GVC 160
6	713 000 006	1	Handrail K-GS
7	C04229 R00	1	Control panel WeeD0
8	C04222 R00	1	Splash guard

2 Overview of Modules


2.1 Assembly for WeeDo - C04220 R00



Parts list - Assembly for WeeDo- C04220 R00


No.	Art.-No.	Num.	Designation
1	713 000 006	1	Handrail K-GS
2	820 000 080	1	Hood hand rail
3	820 000 040	1	Threaded rod
4	820 000 050	2	Spacer tube
5	909 100 262	1	Compression spring
6	941 300 634	2	Butterfly nut
7	C04232	1	Hed wheels
8	820 000 060	2	Clamping disc
9	820 000 061	2	Clamping disc
10	908 008 730	1	Adjusting spring
11	908 706 652	2	Cable grommet double-sided
12	901 806 010	1	Cylinder head screw with Innen skt.
13	901 006 016	1	Skt.-screw without shank
14	905 006 000	1	Spring washer
15	905 106 000	2	Washer
16	900 106 000	1	Washer
17	900 006 002	1	Stop Mother
18	901 008 020	4	Skt.-screw without shank
19	901 008 025	4	Skt.-screw without shank
20	901 008 035	1	Skt.-screw without shank
21	901 008 040	3	Skt. Screw with shank
22	905 108 000	23	Washer
23	900 008 002	11	Stop Mother
24	901 010 025	3	Skt.-screw without shank
25	905 110 000	2	Washer
26	900 010 002	2	Stop Mother
27	900 010 001	1	Hexagon nut
28	901 012 025	1	Skt.-screw without shank
29	905 012 000	1	Spring washer

2.2 Basic housing for WeeDo - C04228 R00




No.	Art.-No.	Num.	Designation
1	C04146	1	Headers
2	C02364	1	Dipstick
3	926 140 484	2	tire
4	906 911 025	2	circlip
5	-	2	Wheel cover
6	713 020 040	2	spacer
7	937 200 010	1	filter element
8	110 000 135	1	Filter carrier in the tank
9	937 105 830	1	seal
10	908 706 667	1	cable grommet
11	936 400 010	1	shut-off valve
12	909 200 021	1	mainspring
13	907 205 040	1	cotter
14	On demand	1	nameplate
15	901 006 025	1	Skt.-screw without shank
16	901 006 045	2	Skt. Screw with shank
17	905 106 000	4	Washer
18	905 206 025	1	K-disc
19	900 006 002	3	Stop Mother
20	915 353 930	2	Plain bearing without collar

2.3 Attachment for WeeDo - C04221 R01




No.	Art.-No.	Num.	Designation
1	C04335	1	Mounting frame compl.
2	C03324	1	Frame hydraulic motor
3	C03326	2	Socket angle adjustment
4	C03328	1	threaded rod
5	935 102 080	1	hydraulic motor
6	941 245 331	1	Three star grip
7	941 200 110	1	clamping lever
8	901 010 055	2	Skt.-screw without shank
9	900 010 001	3	Hexagon nut
10	900 010 003	1	Hat mother
11	901 012 035	1	Skt.-screw without shank
12	901 012 040	2	Skt.-screw without shank
13	901 012 035	2	Hexagon screw
14	905 112 000	6	Washer
15	905 212 001	4	K-disc
16	900 012 002	1	Hexagon nut
17	900 012 001	1	Hexagon nut
18	900 012 002	3	Stop Mother

2.4 Honda Motor GVC 160 WeeDo H - C04227 R00




No.	Art.-No.	Num.	Designation
1	C04161	1	Bellhousing
2	934 100 054	1	Hydraulic pump
3	925 103 019	1	Clutch hub, pump side
4	925 102 064	1	Coupling driver
5	925 101 025	1	Clutch motor.
6	902 305 008	1	Grub screw
7	908 047 420	1	Adjusting spring
8	705 302 343	1	Spacer bushing
9	920 000 055	1	Honda engine
10	901 006 025	4	Skt.-screw without shank
11	905 108 000	8	Washer
12	905 006 000	4	Spring washer
13	900 006 001	4	Hexagon nut

2.5 Control panel for WeeDo - C04229 R00




No.	Art.-No.	Num.	Designation
1	820 000 030	1	Hand Holm
2	908 706 665	1	Grommet
3	941 908 015	2	Handle
4	941 820 164	1	Lever with Bowden cable
5	941 130 712	1	Throttle

2.6 Splash guard WeeDo - C04222 R00




No.	Art.-No.	Num.	Designation
1	C04133	1	Protection sheet
2	C04136	1	Splash guard holder
3	C04230	1	Rubber splash flap
4	700 001 149	1	mounting strip
5	941 200 106	1	clamping lever
6	943 125 252	1	protective cap
7	901 006 020	3	Skt.-screw without shank
8	905 106 000	6	Washer
9	900 006 002	3	Stop Mother

1.4 Brush plate with trimming - C04223 R01




No.	Art.-No.	Num.	Designation
1	C03330	1	brush plate
2	700 000 130	1	Flange brush plate
3	see para.	4 or 8	trimming
4	901 008 025	6	Hexagon head screw,
5	905 108 000	20	Washer
6	900 008 002	14	Stop Mother

1.4 Hydraulic diagram for WeeDo - C04231 R00




No.	Art.-No.	Num.	Designation
1	930 750 040	1	Hydraulic hose
2	930 750 041	1	Hydraulic hose
3	930 750 042	1	Hydraulic hose
4	930 750 043	1	Hydraulic hose
5	930 750 044	1	Hydraulic hose
6	930 750 045	1	Hydraulic hose
7	936 500 538	1	Pressure relief valve
8	931 071 214	2	Hydraulic connection
9	931 031 238	1	Hydraulic connection
10	931 071 238	3	Hydraulic connection
11	931 071 538	1	Hydraulic connection
12	931 041 200	3	Hydraulic connection
13	931 061 200	1	Hydraulic connection

3 Types of trimmings and fortifications

No.	Art.-No.	Foto	Designation
1	700 000 136		Tightrope
2	700 000 135		Tuft combined
3	700 000 137		Tufts flax
4	700 000 132		If he keeps tuft outside
5	700 001 133		He stops tuft Innent hurry

4 Accessories

4.1 Shippers Imitate – C05458 R00



No.	Art.-No.	Num.	Designation
1	C05361	1	Spar
2	901 208 012	4	Countersunk headrest. with interior.

NOTE:



Distributed in UK by
Kersten (UK) Ltd Tel. 0118 986 9253

Progress House
39 Boulton Road Reading, RG2 0NH
www.kerstenuk.com - info@kerstenuk.com